

9. Operating temperature (工作温度):  $-40^{\circ}\text{C}\sim+50^{\circ}\text{C}$

10. Storage temperature (贮存温度):

1-10mm

